

2926 Piper Drive Vero Beach, FL, U.S.A. 32960

SERVICE NO. 1197E BULLETIN

PIPER CONSIDERS COMPLIANCE MANDATORY

Date: November 2, 2017 (S) (M)

SB 1197E supersedes SB 1197D in its entirety. Aircraft that were previously made compliant with SB 1197, SB 1197A, SB 1197B, SB 1197C, or SB 1197D are in compliance with SB 1197E.

SUBJECT:

REASON FOR REVISION:

MODELS AFFECTED:

PA-28-140 Cherokee Cruiser

PA-28-150 Cherokee PA-28-160 Cherokee PA-28-180 Cherokee

PA-28S-160 Cherokee PA-28S-180 Cherokee

PA-28-235 Cherokee Pathfinder

PA-28-235 Cherokee Pathfinder

PA-28-236 Dakota

PA-28-151 Warrior PA-28-161 Cadet PA-28-161 Warrior II

PA-28-161 Warrior III PA-28-180 Archer PA-28-181 Archer II

PA-28-181 Archer III PA-28-201T Turbo Dakota PA-28R-180 Arrow

CONTROL WHEEL SHAFT INSPECTION

SB 1197E adds a caution and corrects minor errors, and includes minor changes for clarity and current document format.

SERIAL NUMBERS AFFECTED:

28-20001 through 28-26946; 28-7125001 through 28-7725290

28-03; 28-1 through 28-4377 and 28-1760A 28-03; 28-1 through 28-4377 and 28-1760A

28-03; 28-671 through 28-5859; 28-7105001 through 28-7205318 28-1 through 28-1760 and 28-1760A

28-671 through 28-5859;

28-7105001 through 28-7105234

28-10001 through 28-11378;

28-7110001 through 28-7210023

28E-11; 28-7310001 through 28-7710089

28-7911001 through 28-8611008;

2811001 through 2811050

28-7415001 through 28-7715314

2841001 through 2841365

28-7716001 through 28-8216300; 28-8316001 through

28-8616057; 2816001 through 2816109

2816110 through 2816119; 2842001 through 2842305

28-E13; 28-7305001 through 28-7505260

28-7690001 through 28-8690056; 28-8690061;

28-8690062; 2890001 through 2890205

2890206 through 2890231; 2843001 through 2843672

28-7921001 through 28-7921095 28R-30002 through 28R-31270; 28R-7130001 through 28R-7130013

ATA/JASC: 2710

PA-28R-200 Arrow 28R-35001 through 28R-35820; 28R-7135001 through 28R-7135229
PA-28R-200 Arrow II 28R-7235001 through 28R-7635545
PA-28R-201 Arrow III 28R-7737002 through 28R-7837317:

2837001 through 2837061; 2844001 through 2844138

PA-28R-201T Turbo Arrow III 28R-7703001 through 28R-7803374;

2803001 through 2803012

PA-28RT-201 Arrow IV 28R-7918001 through 28R-7918267 PA-28RT-201 Arrow IV 28R-8018001 through 28R-8218026 PA-28RT-201T Turbo Arrow IV 28R-7931001 through 28R-8631005;

2831001 through 2831038

PA-32-260 Cherokee Six 32-03; 32-04; 32-1 through 32-1297;

32-7100001 through 32-7800008

PA-32-300 Cherokee Six 32-15; 32-21; 32-40000 through 32-40974;

32-7140001 through 32-7940290

PA-32S-300 Cherokee Six Seaplane 32S-15; 32S-40000 through 32S-40974;

32S-7140001 through 32S-7240137

PA-32R-300 Lance 32R-7680001 through 32R-7880068 PA-32RT-300 Lance II 32R-7885002 through 32R-7985106

PA-32RT-300T Turbo Lance II 32R-7787001; 32R-7887002 through 32R-7987126

PA-32R-301 Saratoga SP 32R-8013001 through 32R-8613006;

3213001 through 3213028; 3213030 through 3213041

PA-32R-301 Saratoga II HP 3213029; 3213042 through 3213103;

3246001 through 3246217; 3246219; 3246223

PA-32R-301 Saratoga II HP (with Entegra) 3246218; 3246220 through 3246222;

3246224 through 3246244

PA-32R-301T Turbo Saratoga SP 32R-8029001 through 32R-8629008;

3229001 through 3229003

PA-32-301 Saratoga 32-8006002 through 32-8606023;

3206001 through 3206019; 3206042 through 3206044;

3206047; 3206050 through 3206055; 3206060

PA-32-301T Turbo Saratoga 32-8024001 through 32-8424002
PA-32R-301T Saratoga II TC 3257001 through 3257483
PA-32-301FT Piper 6X 3232001 through 3232074

PA-32-301XTC Piper 6XT 3255001 through 3255014; 3255026

PA-32-301XTC Piper 6XT (with Entegra) 3255015 through 3255025; 3255027; 3255051

PA-34-200 Seneca 34-E4; 34-7250001 through 34-7450220

PA-34-200T Seneca II 34-7570001 through 34-8170092 PA-34-220T Seneca III 34-8133001 through 34-8633031;

3433001 through 3433172; 3448001 through 3448037 3448038 through 3448079; 3447001 through 3447029

PA-34-220T Seneca V 3449001 through 3449377

PA-34-220T Seneca IV

PA-44-180 Seminole 44-7995001 through 44-8195026

PA-44-180 Seminole 4495001 through 4495013; 4496001 through 4496251

PA-44-180T Seminole 44-8107001 through 44-8207020

COMPLIANCE TIME: To coincide with next regularly scheduled maintenance event, but not to exceed

the next 100 hours time in service

APPROVAL: The engineering aspects of this service document have been shown to comply

with the applicable Federal Aviation Regulations and are FAA approved.

PURPOSE: Piper has received two field reports of incorrectly-assembled control wheel shafts.

Specifically, the shaft common to the sprocket and the universal joint (both pilot and copilot sides) may not have been inserted fully into the universal joint prior to match-drilling the hole for the taper pin that fastens the shaft to the universal joint. The cause of this condition is unknown. Holes mis-drilled in such a manner may appear visually to be acceptable, when in fact the hole in the shaft may be too close to the end of the shaft, causing a significant reduction in joint strength.

Left uncorrected, this condition could lead to separation of the control wheel shaft,

resulting in loss of pitch and roll control.

This service bulletin provides instructions for a mandatory inspection of the shaft to universal joint interface to ensure that they are assembled correctly on all

aircraft that might be affected.

INSTRUCTIONS:

NOTE: Some steps in these instructions are identified as "required for compliance" (RC). If this service bulletin is mandated by an airworthiness directive (AD), the steps identified as RC must be done to comply with the AD. Steps not identified as RC are recommended and may be deviated from, done as a part of other actions, or done with accepted methods different from those given in this service bulletin, if the RC steps can be done and the airplane can be put back in a serviceable condition.

- RC Gain access to the forward end of the control wheel column between the instrument panel and the forward firewall.
- Locate the shaft and the universal joint (2 per aircraft), which are fastened together with a threaded taper pin, as shown in Figures 1 and 2. These components are installed on the aft side of the T-bar assembly.
 - NOTE: Some early model aircraft may have a hex head bolt installed, instead of a taper pin. In both cases, inspection is required to verify adequate edge distance for the hole in the shaft.
 - <u>NOTE</u>: Each universal joint must be fastened to the mating shaft with either a taper pin or a bolt. Any other configuration does not conform to type design.
- 3. RC Inspect each universal joint for the presence of a witness hole, as shown in Figure 2. Most aircraft will have this witness hole feature. However, some early model aircraft may not have a witness hole. If no witness hole exists, proceed to step 5.
- 4. RC Insert a 3/64 inch diameter drill rod into each witness hole as far as it will go with hand pressure. Measure the depth of penetration:
 - If the drill rod penetration depth measures approximately 0.2 inches, this indicates that the drill rod is bottoming out against the near side of the fully inserted shaft. This installation is correct. Proceed to step 9.
 - If the drill rod penetration depth exceeds 0.2 inches, this indicates that the drill rod is bottoming out against the far side inner wall of the universal joint, and is not making contact with the shaft. Universal joints with this condition may have a shaft with inadequate edge distance, and will require further inspection. Proceed to step 5.b.

5. RC - Additional Inspection

If the inspection from step 3 identifies a universal joint without a witness hole, perform the instructions in either step 5.a or step 5.b, at the operator's discretion.

If the inspection from step 4 identifies a shaft with potentially inadequate edge distance, perform the instructions in step 5.b.

- a. Witness hole drilling procedure
 - 1) Order Witness Hole Drill Fixture, Piper part number (P/N) 766-585.
 - 2) Temporarily remove the taper pin (or bolt, as applicable). See Figures 4 and 5, Views A and B.
 - 3) Temporarily pin the Witness Hole Drill Fixture, P/N 766-585, over the universal joint by installing the 400-453 bolt through the hole in the universal joint created by the removal of the taper pin (or bolt, as applicable), from step 5.a.2), directly above. Install 404-534 nut, finger tight.

NOTE: The Bolt, P/N 400-453, and Nut, P/N 404-534, are components of Witness Hole Drill Fixture, P/N 766-585. See Figure 5, View C.

NOTE: P/N 766-585 should fit over the universal joint with little or no relative movement possible. If necessary, temporarily wrap masking tape around the outside of the universal joint to increase the outside diameter, and enable a snug fit prior to proceeding to step 4) below.

WARNING: WEAR EYE PROTECTION WHEN DRILLING.

- 4) Using a #40 drill bit (0.098 inch diameter) and P/N 766-585 for alignment, drill a witness hole in the universal joint, to a depth of 0.185 to 0.235 inches measured from the outer surface of the universal joint.
- 5) Remove P/N 766-585 and insert a 3/64 inch diameter drill rod into the newly created witness hole as far as it will go with hand pressure. Measure the depth of penetration:
 - If the drill rod penetration depth measures 0.235 inches or less, this indicates that the drill rod is bottoming out against the near side of the fully inserted shaft. This installation is correct. Proceed to step 8.
 - If the drill rod penetration depth exceeds 0.235 inches, this indicates that the drill rod is bottoming
 out against the far side inner wall of the universal joint, and is not making contact with the shaft.
 Universal joints with this condition may have a shaft with inadequate edge distance, and will require
 further inspection. Proceed to step 5.b.
- b. Disassembly and components measurement

Temporarily remove the taper pin (or bolt, as applicable) and disassemble the universal joint from the shaft. Then, measure from the end of the shaft to the taper pin (or bolt) hole.

- If the distance from the end of the shaft to the centerline of the hole for the taper pin (or bolt) measures 0.19 inches or more, the edge distance is adequate, and existing parts may be reassembled. Proceed to step 7.
- If the distance from the end of the shaft to the centerline of the hole for the taper pin (or bolt) measures less than 0.19 inches, the edge distance is inadequate, and replacement of the shaft is required. Proceed to step 6.
- 6. If the inspection from step 5 identifies a shaft that must be replaced, identify and order the correct replacement shaft using Table 1, 2 or 3, as applicable.

NOTE: In some cases, the replacement part that is delivered to the customer may have a different part number than the one specified in Tables 1 through 3 of this service bulletin. Differences in part numbers may be due to special service requirements, design improvements, or changes in part number naming convention over time. Table 4 provides all part numbers that are acceptable replacements for each part number specified in Tables 1 through 3.

- 7. In addition, replace any universal joint that exhibits damage, corrosion or excessive wear. Mate the shaft to the universal joint using the following procedure:
 - a. For installations using taper pins:
 - Insert shaft into universal joint, to a depth that achieves a minimum of 0.19 inches from the end of the shaft to the centerline of the hole for the taper pin. Drill hole through mated parts at taper pin location, using a #5 (0.2055 inch diameter) drill bit.
 - 2) Ream drilled hole in steps, with a #1 tapered reamer, Piper P/N 906-713. In a properly sized tapered hole, the tapered pin shall install to a depth such that the small end of the tapered shank (where the threads begin) is between 0.030 inches inside and 0.062 inches outside of outer surface.
 - b. For installations using hex head bolts:

Insert shaft into universal joint, to a depth that achieves a minimum of 0.19 inches from the end of the shaft to the centerline of the hole for the bolt. Drill hole through mated parts at bolt location, using a #16 (0.1770 inch diameter) drill bit. Ream hole to final size of 0.1870 to 0.1875 inches in diameter.

8. RC – Reinstall threaded fastener

CAUTION: DO NOT USE FORCE TO DRIVE THE THREADED FASTENER INTO HOLE, AS COMPONENT DAMAGE MAY OCCUR.

a. For taper pins:

Install tapered pin through mated parts. (See Figure 3). Install the appropriate washer under the nut, using the following criteria:

- If pin shoulder (small taper end) does not protrude past outer surface, install an NAS1149F0363P washer (Piper P/N 690-612) under nut.
- If pin shoulder (small taper end) protrudes past tube surface, install an AN975-3 washer (Piper part number 494-093) under nut.

NOTE: Do not reuse the nut that installs the taper pin. Taper pins, washers, sprockets and universal joints may be reused, if they are determined to be in airworthy condition.

b. For hex head bolts:

Install bolt, washer and nut to match original hardware stack up.

NOTE: Do not reuse the nut that installs the bolt. Bolts, washers, sprockets and universal joints may be reused, if they are determined to be in airworthy condition.

9. RC – Make a logbook entry documenting compliance with this service bulletin.




Figure 1
Control Column Assembly




Figure 2
Shaft Fastened to Universal Joint




Figure 3
Taper Pin Protrusion






Figure 4
Witness Hole Drilling Procedure





VIEW C

766-585 WITNESS HOLE DRILL FIXTURE PINNED IN PLACE

Figure 5
Witness Hole Drilling Procedure

MATERIAL REQUIRED: The correct part numbers may be found in the applicable Piper Airplane Parts

Catalog and Tables 1, 2 and 3.

One (1) each, Witness Hole Drill Fixture, P/N 766-585 (includes nut and bolt)

AVAILABILITY OF PARTS: Your Piper Approved Service Center

EFFECTIVITY DATE: This service bulletin is effective upon receipt.

SUMMARY: Please contact your Piper Approved Service Center to make arrangements for

compliance with this service bulletin in accordance with the compliance time

indicated.

NOTE: Please notify the factory of any address/ownership corrections. Changes should include aircraft model,

serial number, and current owner's name and address.

Corrections and/or changes should be directed to:

PIPER AIRCRAFT, INC. Att'n: Customer Service

2926 Piper Drive

Vero Beach, FL 32960

or:

CustomerService@piper.com

Please include in subject line: "Aircraft ownership update"

TABLE 1
REPLACEMENT SHAFT AND UNIVERSAL JOINT

		Sh	Shaft	
Model	Serial Number	left	right	Universal
		(Pilot)	(Copilot)	Joint
	28-20001 through 28-20160	62716-002	62716-003	62834-000
	28-20161 through 28-21845			
DA 00 440	28-21931 through 28-21934	62716-004	62716-005	62834-000
PA-28-140	28-21846 through 28-21930		62716-007	62834-002
Cherokee	28-21935 through 28-25400	62716-006		
	28-25401 through 28-26946			
	28-7125001 through 28-7725290	62716-007	62716-007	62834-002
	28-1 through 28-1760		62716-003	62834-000
PA-28-150	28-03, 28-1760A	62716-002		
Cherokee	28-1761 through 28-3377	62716-004	62716-005	62834-000
	28-3378 through 28-4377	62716-006	62716-007	62834-002
	28-1 through 28-1760		62716-003	
PA-28-160	28-03, 28-1760A	62716-002		62834-000
Cherokee	28-1761 through 28-3377	62716-004	62716-005	62834-000
	28-3378 through 28-4377	62716-006	62716-007	62834-002
	28-671 through 28-1760	00740 000	00740 000	00004.000
	28-03	62716-002	62716-003	62834-000
PA-28-180	28-1761 through 28-3377	62716-004	62716-005	62834-000
Cherokee	28-3378 through 28-4377	62716-006	62716-007	62834-002
	28-4378 through 28-5859	00740 007	62716-007	62834-002
	28-7105001 through 28-7205318	62716-007		
PA-28S-160	28-1 through 28-1760	62716-002	62716-003	62834-000
Cherokee	28-1760A	02/10-002	02710-003	02034-000
	28-671 through 28-1760	62716-002	62716-003	62834-000
PA-28S-180	28-1761 through 28-3377	62716-004	62716-005	62834-000
Cherokee	28-3378 through 28-4377	62716-006	62716-007	62834-002
Cherokee	28-4378 through 28-5859	62716-007	62716-007	62834-002
	28-7105001 through 28-7105234	02710-007		
	28-10001 through 28-10486	62716-002	62716-003	62834-000
	28-10487 through 28-10719	62716-004	62716-005	62834-000
PA-28-235	28-10720 to 28-11039	62716-006	62716-007	62834-002
Cherokee	28-11040 through 28-11378			
	28-7110001 through 28-7210023	62716-007	62716-007	62834-002
	28E-11			
	28-7310001 through 28-7710089			
PA-28-236	28-7911001 through 28-8611008	62716-007	62716-007	62834-002
Dakota	2811001 through 2811050	027 10-007	027 10-007	02034-002
PA-28-151	28-7415001 through 28-7715314	62716-007	62716-007	62834-002
Warrior	20 7 - 1000 1 tillough 20-77 10014	327 10-007	021 10-001	0200∓∃002
PA-28-161	2841001 through 2841365	62716-007	62716-007	62834-002
Cadet	<u> </u>	027 10-007	027 10-007	02004-002
PA-28-161 Warrior II	28-7716001 through 28-8216300			
	28-8316001through 28-8616057			
	2816001 through 2816109	62716-007	62716-007	62834-002
	2816110 through 2816119			
	2842001 through 2842305			

TABLE 2
REPLACEMENT SHAFT AND UNIVERSAL JOINT

	T	Shaft		T
Model	Serial Number	left (Pilot)	right (Copilot)	Universal Joint
PA-28-161	2816110 through 2816119	, ,	, ,	
Warrior III	2842001 through 2842305	62716-007	62716-007	62834-002
PA-28-180	28-E13			
Archer	28-7305001 through 28-7505260	62716-007	62716-007	62834-002
	28-7690001 through 28-8690056			
PA-28-181	28-8690061, 28-8690062	62716-007	62716-007	62834-002
Archer II	2890001 through 2890205			
PA-28-181	2890206 through 2890231	60746 007	60746 007	62024 002
Archer III	2843001 through 2843672	62716-007	62716-007	62834-002
PA-28-201T	28-7921001 through 28-7921095	62716-007	62716-007	62834-002
Turbo Dakota	26-7921001 tillough 26-7921095	027 10-007	027 10-007	
PA-28R-180	28R-30002 through 28R-31270	62716-007	62716-007	62834-002
Arrow	8R-7130001 through 28R-7130013	027 10-007	02710-007	02034-002
PA-28R-200	28R-35001 through 28R-35820	62716-007	62716-007	62834-002
Arrow	28R-7135001 through 28R-7135229	027 10-007	02710-007	
PA-28R-200	28R-7235001 through 28R-7635545	62716-007	62716-007	62834-002
Arrow II	•	027 10 007	027 10 007	0200+ 002
PA-28R-201	28R-7737002 through 28R-7837317			
Arrow III	2837001 through 2837061	62716-007	62716-007	62834-002
	2844001 through 2844138			
PA-28R-201T	28R-7703001 through 28R-7803374	62716-007	62716-007	62834-002
Turbo Arrow III	2803001 through 2803012			
PA-28RT-201	28R-7918001 through 28R-7918267	62716-007	62716-007	7 62834-002
Arrow IV	28R-8018001 through 28R-8218026			
PA-28RT-201T	28R-7931001 through 28R-8631005	62716-007	62716-007	7 62834-002
Turbo Arrow IV	2831001 through 2831038			
	32-03, 32-04	62716-004	62716-005	62834-000
PA-32-260	32-1 through 32-600 32-601 through 32-690	62716-006	62716-007	62834-002
Cherokee Six	32-691 through 32-1297	027 10-000	027 10-007	02034-002
	32-7100001 through 32-7800008	62716-007	62716-007	62834-002
	32-15, 32-21	62716-004	62716-005	62834-000
PA-32-300	32-40000 through 32-40415	62716-004	62716-003	62834-002
Cherokee Six	32-40416 through 32-40974			
	32-7140001 through 32-7940290	62716-007	62716-007	62834-002
	32S-15	62716-004	62716-005	62834-000
PA-32S-300	32S-40000 through 32S-40415	62716-006	62716-007	62834-002
Cherokee Six	32S-40416 through 32S-40974	62716-007	62716-007	62834-002
Seaplane	32S-7140001 through 32S-7240137			
PA-32R-300	•	62716-007	00740 007	00004 000
Lance	32R-7680001 through 32R-7880068		62716-007	62834-002
PA-32RT-300	22D 7005002 through 22D 7005400	60746 007	60746 007	62024 002
Lance II	32R-7885002 through 32R-7985106	62716-007	62716-007	62834-002
PA-32RT-300T	32R-7787001	62716-007	62716-007	62834-002
Turbo Lance II	32R-7887002 through 32R-7987126	027 10-007	02710-007	02034-002

TABLE 3
REPLACEMENT SHAFT AND UNIVERSAL JOINT

		Shaft		l lucius na al
Model	Serial Number	left (Pilot)	right (Copilot)	Universal Joint
PA-32R-301 Saratoga SP	32R-8013001 through 32R-8613006 3213001 through 3213028 3213030 through 3213041	62716-007	62716-007	62834-002
PA-32R-301 Saratoga II HP	3213029 3213042 through 3213103 3246001 through 3246217 3246219; 3246223	62716-007	62716-007	62834-002
PA-32R-301 Saratoga II HP (with Entegra)	3246218 3246220 through 3246222 3246224 through 3246244	62716-007	62716-007	62834-002
PA-32R-301T Turbo Saratoga SP	32R-8029001 through 32R-8629008 3229001 through 3229003	62716-007	62716-007	62834-002
PA-32-301 Saratoga	32-8006002 through 32-8606023 3206001 through 3206019 3206042 through 3206044 3206047 3206050 through 3206055 3206060	62716-007	62716-007	62834-002
PA-32-301T Turbo Saratoga	32-8024001 through 32-8424002	62716-007	62716-007	62834-002
PA-32R-301T Saratoga II TC	3257001 through 3257483	62716-007	62716-007	62834-002
PA-32-301FT Piper 6X	3232001 through 3232074	62716-007	62716-007	62834-002
PA-32-301XTC Piper 6XT	3255001 through 3255014 3255026	62716-007	62716-007	62834-002
PA-32-301XTC Piper 6XT (with Entegra)	3255015 through 3255025 3255027, 3255051	62716-007	62716-007	62834-002
PA-34-200 Seneca	34-E4 34-7250001 through 34-7450220	62716-007	62716-007	62834-002
PA-34-200T Seneca II	34-7570001 through 34-8170092	62716-007	62716-007	62834-002
PA-34-220T Seneca III	34-8133001 through 34-8633031 3433001 through 3433172 3448001 through 3448037	62716-007	62716-007	62834-002
PA-34-220T Seneca IV	3448038 through 3448079 3447001 through 3447029	62716-007	62716-007	62834-002
PA-34-220T Seneca V	3449001 through 3449377	62716-007	62716-007	62834-002
PA-44-180 Seminole	44-7995001 through 44-8195026 4495001 through 4495013 4496001 through 4496251	62716-007	62716-007	62834-002
PA-44-180T Seminole	44-8107001 through 44-8207020	62716-007	62716-007	62834-002

TABLE 4
ACCEPTABLE REPLACEMENT SHAFT AND UNIVERSAL JOINT PART NUMBERS

Piper Part Number (as stated in Table 1)	Acceptable Replacement Part Numbers		
62716-002	62716-2 62716-02		
62716-003	62716-3 62716-03 62716-7 62716-07 62716-007		
62716-004	62716-4 62716-04		
62716-005	62716-5 62716-05 62716-7 62716-07 62716-007		
62716-006	62716-6 62716-06		
62716-007	62716-7 62716-07		
62834-000	62834 62834-0 62834-00		
62834-002	62834-2 62834-02 62834-802		



Aircraft Certification Service Compliance & Airworthiness Division Atlanta ACO Branch 1701 Columbia Ave. College Park, Georgia 30337

November 29, 2017

In Reply, Reference FAA Correspondence #7A0-17-2662

Mr. Eric A. Wright
ODA Administrator
The Piper Aircraft, Inc
2926 Piper Drive
Vero Beach, Florida 32960

Subject: Alternative Method of Compliance (AMOC) for Airworthiness Directive 2010-15-10, Paragraphs (e) and (h).

Dear Mr. Wright:

The Federal Aviation Administration (FAA) received your proposal dated November 6, 2017, proposing an alternative method of compliance (AMOC) to paragraphs (e) and (h) of Airworthiness Directive 2010-15-10 for Piper Model PA-28, PA-32, PA-34, and PA-44 aircraft. This AD requires owners/operators to inspect the control wheel shaft on both the pilot and copilot sides and replace the control wheel shaft as required.

Your letter indicated that Piper Service Bulletin (SB) 1197E has superseded SB1197D, SB1197C, SB 1197B, SB 1197A and requested that SB 1197E be accepted as an AMOC to AD 2010-15-10.

The Atlanta Aircraft Certification Office approves your AMOC proposal. The ACO has reviewed SB 1197E and has determined that it provides an acceptable level of safety and may be used in lieu of SB 1197A, SB 1197B, SB1197C, and SB1197D when complying with AD 2010-15-10 paragraphs (e) and (h).

This AMOC does not relieve any other requirements of the AD.

When complying with AD 2010-15-10 using this alternative method of compliance, a copy of this letter shall be inserted into the maintenance records of the airplane. Please include a copy of this AMOC when distributing SB 1197E.

This FAA AMOC is transferable with the aircraft to another owner/operator.

Before using this AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/Certificate Holding District Office.

The preceding paragraph also applies to any applicable foreign-registered aircraft upon transfer of the aircraft to the U.S. registry if compliance with the AMOC has not been accomplished.

Should you have any questions or concerns, please feel free to contact me at 404-474-5587 or via email at Hector.Hernandez@FAA.gov.

Sincerel

Christina M. Underwood

Manager, Atlanta ACO Branch

CC:

1. Transport Canada

2. European Aviation Safety Agency (EASA)