

SERVICE BULLETIN**SB15-5**

Contains Useful Information Pertaining To Your Aircraft Engine

**TECHNICAL PORTIONS
FAA APPROVED****SUBJECT:** Champion Aerospace SLICK Service Letter
SL No. 4300/6300-74-20-001**PURPOSE:** Ignition - Distribution - Slick Magneto Supplemental Timing Inspection
Information**COMPLIANCE:** As listed in attached Champion Aerospace Service Letter, time in service
sensitive.**MODELS****AFFECTED:** All Continental Motors (CM) O-200, IO-240, IO-360, TSIO-360, LTSIO-360,
O-470, IO-470, IO-520, LTSIO-520, TSIO-520, IO-550, TSIO-550, and TSIOL-
550 series aviation gasoline (AvGas) engines using SLICK 4300 series or 6300
series magnetos.**I. GENERAL INFORMATION**

To inform owner / operators that Champion Aerospace has issued SLICK Service Letter “SL No. 4300/6300-74-20-001” recommending ignition system inspection procedures concerning magneto drift in engine timing. Please reference the Champion Aerospace attachment for detailed compliance information.

For your convenience, please use the following cross-reference table to identify affected Continental Motors (CM) Part Numbers:

Part Numbers	
SLICK	CM
4301	653262
4309	655367
4310	655368
6310	653267
6314	653271
6320	653280
6324	653292

ISSUED	REVISED	 P.O. Box 90 Mobile, AL 251-436-8299	PAGE NO	DOC NO	REVISION
2015/10/06			1 of 2	SB15-5	

Intentionally Left Blank

ISSUED	REVISED		PAGE NO	DOC NO	REVISION
2015/10/06		P.O. Box 90 Mobile, AL 251-436-8299	2 of 2	SB15-5	