

Vero Beach, Florida, U.S.A.

FAA Approved

SERVICE No. 804 BULLETIN PIPER CONSIDERS COMPLIANCE MANDATORY.

April 26, 1985

SUBJECT:

MODELS AFFECTED:

PA-28-180 Archer PA-28-181 Archer II PA-28-201T Turbo Dakota PA-28-235 Pathfinder PA-28-236 Dakota PA-28R-200 Arrow PA-28R-201 Arrow III PA-28R-201T Turbo Arrow IV PA-32-301T Turbo Saratoga Battery Strap Installation

SERIAL NUMBERS AFFECTED:

28-7505001 through 28-7505259 28-7690001 through 28-8590035 28-7921001 through 28-7921091 28-7510001 through 28-7710089 28-7911001 through 28-8511006 28R-7535001 through 28R-7635545 28R-7737001 through 28R-7837317 28R-7703001 through 28R-7803373 28R-7931001 through 28R-8531007 32-8024001 through 32-8424002

<u>COMPLIANCE TIME</u>: To coincide with the next regularly scheduled inspection event, but not to exceed the next one-hundred (100) hours of operation.

PURPOSE: Reports have been received of the battery becoming dislodged from the battery box due to overloads imposed in severe turbulence or in a crash sequence.

This Service Bulletin announces the availability of a Battery Strap Installation Kit that, when installed, will decrease the potential for the battery dislodging under the condition described above.

INSTRUCTIONS: All instructions necessary to accomplish this modification are contained in the Battery Strap Installation Kit, Piper Part Number 765-157.

MATERIAL REQUIRED: One (1) each Battery Strap Installation Kit, Piper Part Number 765-157, per aircraft.

AVAILABILITY OF PARTS: Your Piper Field Service Facility.

EFFECTIVITY DATE: This Service Bulletin is effective upon receipt.

SUMMARY: Please contact your Piper Field Service Facility to make arrangements for compliance with this Service Bulletin.

Any applicable factory participation will be in effect for a period of time not to exceed 180 days from the date of this Service Bulletin.

NOTE: If you are no longer in possession of this aircraft, please forward this information to the present owner.

ATA: 2430