

Subject:

SERVICE LETTER

Flap Warning Placard

Piper Aircraft Corporation

"DOA SO-1 Approved"

Lock Haven, Pennsylvania, U.S.A. January 6, 1977 S/M

	. 6
Models Affected:	Serial Numbers Affected:
PA-28-140 Cherokee PA-28-150 Cherokee PA-28-151 Cherokee Warrior PA-28-160 Cherokee PA-28-180 Cherokee	28-1 to 28-4377 Inclusive 28-7415001 to 28-7715295 Inclusive 28-1 to 28-4377 Inclusive 28-671 to 28-7505259 Inclusive
PA-28R-180 Cherokee Arrow	
PA-28R-200 Cherokee Arrow II	28R-35001 to 28R-7735498 Inclusive
PA-28R-201 Cherokee Arrow III PA-28R-201T Cherokee Arrow T	28R-7703001 to 28R-7703008 Inclusive
PA-28-235 Cherokee	

PA-32-300 Cherokee Six...... 32-40001 to 32-7740028 Inclusive PA-32R-300 Cherokee Lance 32R-7680001 to 32R-7780121 Inclusive

Compliance Time:

At Owner/Operator's discretion.

Purpose: Reports from the field indicate the need of a placard that will warn persons boarding or deplaning any of the above affected aircraft of the flaps being partially extended or unlocked.

This Service Letter announces the availability of the above referenced placard that, when installed, will warn people of this condition.

Instructions: Apply placard per attached instructions data.

Material Required: One (1) each per aircraft, Piper Part Number 35664-02 Warning Placard @ suggested unit list price \$.65C.


Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Letter is effective upon receipt.

Summary: Please contact your Piper Service Facility to make arrangements for compliance with this Product Refinement feature.



NOTE: If required, it is permissible to trim forward edge of flap step material in order to install the placard at the dimensions shown. Seal trimmed edge with 3M Edge Sealing Compound #62-5569-2660-8 (5 oz. Tube - Piper P/N 914 055).