



# SERVICE LETTER

No. 848

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

FAA DOA SO-1 Approved

June 21, 1978

S

This Service Release supercedes Part V of Service Letter No. 814 dated September 26, 1977

Reason for Revision:

Compliance Time Changed

Subject:

Exhaust Heat Shield

Models Affected:

Serial Numbers Affected:

PA-28R-201T Turbo Arrow III

28R-7703001 through 28R-7803276 Inclusive

Compliance Time:

At the next scheduled inspection interval (100 hour annual or programmed inspection event, whichever occurs first) not to exceed the next 100 hours of operation.

Purpose:

This Service Release announces the availability of an improved Exhaust Heat Shield replacement for existing Piper Part Number 486 648 Heat Shield.

Instructions:

Contained in the Kit specified in Material Required, below.

Material Required:

One (1) each 763 843V Kit.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Letter is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to make arrangements to install the above referenced Kit in the affected aircraft in accordance with the provisions of Compliance Time, above. Providing installation arrangements are conducted through your Piper Field Service Facility, reimbursement for material is available for affected aircraft for a period of six (6) months from the date of this release.