RGL Home

Airworthiness Directive

Federal Register Information

▼Header Information DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

Amendment 39-3363; AD 78-25-03

Airworthiness Directives; THE DEUTSCH COMPANY, METAL COMPONENTS DIVISION: Applies to P/N 94B0100004F0160 and 94F0100004F0166 Hose Assemblies Marked With Identification 4Q77 or 1Q78 PDF Copy (If Available):

▼Preamble Information

DATES: Effective January 15, 1979.

▼Regulatory Information

78-25-03 THE DEUTSCH COMPANY, METAL COMPONENTS DIVISION: Amendment 39-3363. Applies to P/N 94B0100004F0160 and 94F0100004F0166 hose assemblies marked with identification 4Q77 or 1Q78 which may be installed on various aircraft but which are known to be installed on Piper Models PA-23-250, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-31, PA-31-300, PA-31-325, PA-31-350, PA-31P, PA-31-TI, PA-31-T, PA-34-200T, and PA-44-180 aircraft.

NOTE 1: Hose P/N and manufacturing date codes (e.g. 4Q77 and 1Q78) are shown on a metal tag attached to the hose assemblies.

1 of 3 9/17/2019, 10:21 PM

- a) Deutsch P/N 94B0100004F0160 is Piper P/N 17766-27, TSO C-53a Type A.
- b) Deutsch Part No. 94F0100004F0166 is Piper P/N 63901-41, TSO C-53a Type C.

Compliance required as indicated, unless already accomplished.

To prevent an unsafe condition in the various aircraft systems in which these hoses may be installed, accomplish the following:

A. Within the next ten hours time in service after the effective date of this (AD), inspect to determine if hose assembly P/N 94B0100004F0160 or 94F0100004F0166 with manufacturing date 4Q77 or 1Q78 is installed.

- B. If the hose assemblies as in A above are not installed no further action is required by this (AD).
- C. If the hose assemblies in A above are installed, prior to further flight,
- (1) Remove and replace hose assemblies.
- (2) Check system for contamination. Purge system if evidence of contamination is found.

NOTE 2: Piper Service Bulletin No. 611 refers to purging procedures for Piper Models PA -28, -34, and -44. Piper Service Bulletin No. 629 refers to purging procedures for Piper Models PA-31 and PA-23.

NOTE 3: The following is a list of Piper Model, Serial Nos. and hose application which are believed to have suspect hoses installed. Possible hose application is not limited to this list.

<u>Model</u>	<u>Serial Number</u>	<u>Application</u>	Qty. of hoses
PA-23-250	27-7854007 thru	Pressure nose gear cylinder	2
Aztec F	27-7954018	up and pressure anti-retract	
		valve	
PA-28R-180	Possible Retrofit	NLG actuating cylinder	2
PA-28R-200	Possible Retrofit	NLG actuating cylinder	2
PA-28R-201	78-37105 thru 78-37317	NLG actuating cylinder	2
PA-28R-201T	78-03154 thru 78-03372	NLG actuating cylinder	2
		Manifold pressure at left hand	1
		rear of engine	
PA-31	31-1 thru 31-7812122	Main landing gear actuating	2
	and	cylinders	
	31-5001 thru 31-7852166		
PA-31-300	Possible Retrofit	Main landing gear actuating cylinders	2
PA-31-325	31-7812016 thru	Main landing gear actuating	2
Navaho C/H	31-7912004	cylinders	
PA-31-350	Possible Retrofit	Main landing gear actuating	2
& PA-31-P		cylinders	
PA-31TI	31T-7804001 thru	Main landing gear actuating	2
Cheyenne I	31T-7904006	cylinders	

2 of 3 9/17/2019, 10:21 PM

PA-31T	31T-77200069	Main landing gear actuating	2
Cheyenne,	thru	cylinders	
Cheyenne II	31T-7920012		
PA-34-200T	78-70100 thru 78-70474	Fuel drains	4
PA-44-180	79-95001 thru 79-95127	Engine oil pressure line at	2
		filter	

- D. Special flight permits may be issued in accordance with FARs 21.197 and 21.199 to operate aircraft to a base for the accomplishment of the inspection required by paragraph A of this AD.
- E. Equivalent inspections and repairs may be used when approved by the Chief, Aircraft Engineering Division, FAA Western Region.
- F. Upon submission of substantiating data, through an FAA Aviation Safety Inspector, the Chief, Aircraft Engineering Division, FAA Western Region may adjust the compliance time for hose replacement.

This amendment becomes effective January 15, 1979, for all persons except those to whom it was made effective by priority message dated October 27, 1978.

▼Footer Information

▼Comments

 $\textbf{FAA.gov Home} \mid \textbf{Privacy Policy} \mid \textbf{Web Policies \& Notices} \mid \textbf{Contact Us} \mid \textbf{Help}$

Readers & Viewers: PDF Reader | MS Word Viewer | MS PowerPoint Viewer | MS Excel Viewer | WinZip

3 of 3 9/17/2019, 10:21 PM