

SERVICE NO. 503 SPARES LETTER

Date: September 30, 2022 (S

SUBJECT: LOWER WING SKIN ACCESS PANEL KIT

MODELS AFFECTED: SERIAL NUMBERS AFFECTED:

PA-28-151 Warrior 28-7415001 through 28-7715314

PA-28-161 Warrior II/III 28-7716001 through 28-8616057; 2816001 through

28161119; 2842001 through 2842420

PA-28-161 Cadet 2841001 through 2841365

PA-28-181 Archer II 28-7690001 through 28-8690056, 28-8690061,

28-8690062; 2890001 through 2890205

PA-28-181 Archer III 2890206 through 2890231; 2843001 through 2843939;

2881001 and up

PA-28-181 Pilot 100i 28020001 and up

PA-28-236 Dakota 28-7911001 through 28-8611008; 2811001 through

2811050

PA-28-201T Turbo Dakota 28-7921001 through 28-7921095

PA-28R-201 Arrow III 28R-7737002 through 28R-7837317; 2837001 through

2837061; 2844001 and up

PA-28R-201T Turbo Arrow III 28R-7703001 through 28R-7803372; 2803001 through

2803015

PA-28RT-201 Arrow IV 28R-7918001 through 28R-8218026

PA-28RT-201T Turbo Arrow IV 28R-7931001 through 28R-8631005; 2831001 through

2831038

PURPOSE: This service spares letter announces the availability of a kit that adds an

inspection/access panel to the lower wing skin on both sides of affected aircraft. When installed, the panels permit easier access to the fuel tank sending units.

AVAILABILITY OF PARTS: Your Piper Approved Service Center

SUMMARY: For affected aircraft that do not already have access panels installed that offer

access to the fuel tank sending unit, Piper part number 88666-701, Kit – Lower Wing Skin Inspection Panel, provides the parts and instructions to install access

panels. (Each kit includes the parts for two panel installations.)

ATA/JASC: 5730

NOTE: Please notify the factory of any address/ownership corrections. Changes should include aircraft model, serial number, and current owner's name and address.

Corrections and/or changes should be directed to:

PIPER AIRCRAFT, INC. Attn: Customer Service 2926 Piper Drive Vero Beach, FL 32960

or:

CustomerService@piper.com

Please include in subject line: "Aircraft ownership update"